


BMW X3: 1GEH766

Vinnumber:	WBAWY110100C58020	Versionname:	X3 sDrive18 136PK
First Registrationdate:	15/01/2014	Fiscalpower:	
Expertise Mileage:	95261	Power Kw:	100
Bodytype:	SUV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	01-2018	Parking lot:	3303
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/60/17/99 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------























Total cost ex VAT	1804,66
Bumper F M, Scratch(es), Smart repair	110,64



Door panel R L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Ceiling, Stain, Cleaning	25,00
--------------------------	--------------

			Maintenance, Maintenance, Execute	0,00
			Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
			Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
			Door R L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
			Door F L, Bump(s), PDR - Knock out without painting	63,00
			Wing F L, Scratch(es), LI - Repair and paint (complete)	264,21
			Door R R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
			Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
				
			Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>				
			Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
			Bonnet, Scratch(es), LI - Repair and paint (complete)	348,09
				



Seat cover F R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------

