



RENAULT Laguna: YN8166			
Vinnumber:	VF1KT1RG648870416	Versionname:	LAGUNA BRE ECO2 Champion Sp.Ed.FAP 110PK
First Registrationdate:	8/12/2015	Fiscalpower:	
Expertise Mileage:	129631	Power Kw:	81
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3716
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
GPS storage	SD Luggage cover
GPS storage	Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining semi-artificial leather

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	215/50/17/95 V LightMetal			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes

Total cost ex VAT	1128,20
Door F L, Bump(s), PDR - Knock out without painting	63,00



Bumper R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover R L, Stain, Cleaning	25,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door frame F L, Scratch(es), Acceptable 0,00

No pictures to display

Door moulding Lower F L, Scratch(es), Acceptable 0,00

No pictures to display

Rearlight L tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Scratch(es), E - Replace 487,20



Front bumper, Stone chip(s), Acceptable 0,00

No pictures to display

Seat cover F L, Stain, Cleaning 25,00



Door panel R R, Scratch(es), Acceptable 0,00

No pictures to display

Rear spoiler, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 370,00



Bonnet, Bump(s), PDR - Knock out without painting 63,00

