




VOLVO V40: 1GJE589			
Vinnumber:	YV1MV8461E2140007	Versionname:	V40 D2 Base 115PK
First Registrationdate:	21/02/2014	Fiscalpower:	
Expertise Mileage:	180754	Power Kw:	84
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1116
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	205/50/17/92 H Steel			
Winter tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm


Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT		641,80	
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)		95,00	



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)		95,00
---	--	-------



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Bad repair, Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Dirty, Cleaning 50,00

