



VOLKSWAGEN PASSAT: 1EKM556

Vinnnumber:	WVWZZZ3CZDE085525	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	7/01/2013	Fiscalpower:	
Expertise Mileage:	106610	Power Kw:	77
Bodytype:	Break	Body color:	Beige
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1227
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Sun Roof electric	
Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunctional	Front parking sensors	
Seats F heated	Rear parking sensors	
Radio multimedia	Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection


Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	215/55/16/97 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

	Compressor	Yes
Total cost ex VAT		1326,92
Bonnet, Bump(s), LI - Repair and paint (complete)		386,08



Boot carpet, Damaged, E - Replace	100,00
-----------------------------------	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 301,68

