



**VOLKSWAGEN POLO: 1RHS353**

Vinnnumber:	<b>WVWZZZ6RZHY149209</b>	Versionname:	<b>1.4 TDI 55KW TRENDLINE</b>
First Registrationdate:	<b>30/12/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>21673</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Brown</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>NOT OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>459</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>NOT OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>

**Limited Technical Inspection**

Power steering:	<b>No</b>	Battery functioning:	<b>Yes</b>
Airco functioning:	<b>NOT OK</b>	Sound engine:	<b>NOT OK</b>
Tires wear profile:	<b>OK</b>	Clutch test:	<b>NOT OK</b>
Idle position:	<b>NOT OK</b>	Wiper fluid level:	<b>NOT OK</b>
Engine startingtime:	<b>NOT OK</b>	Lighting:	<b>OK</b>
Exhaust gass:	<b>NOT OK</b>	Wiperblades:	<b>OK</b>
Transmission:	<b>NOT OK</b>		
Handbrake:	<b>NOT OK</b>		

**Degree of wear**

	<b>175/70/14/84 T Steel</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 6 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

**Assistance equipment**

Spare wheel:	<b>Yes</b>	Jack:	<b>Yes</b>
--------------	------------	-------	------------

Total cost ex VAT:	<b>0,00</b>
--------------------	-------------

Registration Document, Missing, E - Replace:	<b>0,00</b>
--	-------------

*No pictures to display*

Bodywork, Damaged, LI - Repair and paint (complete):	<b>0,00</b>
--	-------------





Certificate Of Conformity, Missing, E - Replace	0,00
---	------

*No pictures to display*