



## VOLKSWAGEN Passat: 1EMA914

Vinnumber:	<b>WVWZZZ3CZDE091812</b>	Versionname:	<b>PASSAT VAR Comfortline BMT 105PK</b>
First Registrationdate:	<b>18/01/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>82387</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Green</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2101</b>
Maintenance:	<b>4800KM 173 DAGEN</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

## Options

Radio CD		Seats electric F L
GPS storage		Seats electric F R
GPS storage	<b>HD</b>	Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	
Adaptive cruise control		

## Limited Technical Inspection

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

## Degree of wear

	<b>215/55/16/97 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	786,35
-------------------	--------

Front bumper, Scratch(es), Ll - Repair and paint (complete)	211,80
---	--------





Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 0,00



Door panel R L, Damaged, Smart repair 110,64



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Mirror side blinker R, Crack, E - Replace 30,00



Windscreen, Scratch(es), E - Replace 0,00

