



VOLVO V40: 1EMO575			
Vinnumber:	YV1MV8481D2034011	Versionname:	
First Registrationdate:	23/01/2013	Fiscalpower:	
Expertise Mileage:	51300	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2806
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Pirelli: 7 mm	Fr.R.	Pirelli: 7 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes

Total cost ex VAT	1717,37
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Rearview mirror housing R, Scratch(es), Smart repair	110,64
--	---------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Interior, Dirty, Cleaning 50,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20

