



VOLKSWAGEN Transporter: 1FU167			
Vinnnumber:	<b>WV1ZZZ7HZEX008529</b>	Versionname:	<b>TRANSP.1000 B/F SWB</b>
First Registrationdate:	<b>25/10/2013</b>	Fiscalpower:	<b>140PK</b>
Expertise Mileage:	<b>220050</b>	Power Kw:	<b>103</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3710</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Central consol F
Windows electric F	Rear parking sensors
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining semi-artificial leather</b>

Limited Technical Inspection			
Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

Degree of wear				
	<b>205/65/16/105 T Steel</b>			
Winter tyres:	Fr.L.	<b>Semperit: 8,5 mm</b>	Fr.R.	<b>Semperit: 8,5 mm</b>
	Re.L.	<b>Semperit: 9,9 mm</b>	Re.R.	<b>Semperit: 9,9 mm</b>

Assistance equipment	
Spare wheel	<b>Yes</b> Jack <b>Yes</b>
Total cost ex VAT	769,05
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror R complete, Broken, E - Replace	138,00



Interior, Dirty, Acceptable	0,00
-----------------------------	------



Trunk door R L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	

Bumper F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Bump(s), LI - Repair and paint (complete)	279,15



Trunk door R R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk door R R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Bump(s) and scratch(es), E - Replace	329,40



Door F L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R L, Missing, E - Replace	22,50

