


RENAULT Grand Scenic: 1GAP635

Vinnumber:	VF1JZ14P649976180	Versionname:	GRAND SCENIC Bose Ed.7pl.110PK
First Registrationdate:	9/12/2013	Fiscalpower:	
Expertise Mileage:	182995	Power Kw:	81
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2325
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Adaptive cruise control			

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			744,70
Alloy rim F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Trunk lid covering R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F L, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Sill outer R, Bump(s), LI - Repair and paint (complete)			310,50



Wing R.R. Bump(s), Acceptable

0,00

Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s), PDR - Knock out without painting 63,00



Bonnet, Bump(s), PDR - Knock out without painting 63,00



Seat cover F L, Damaged, Acceptable 0,00



Wing R L, Bump(s), LI - Repair and paint (complete) 308,20



Door F R, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), Acceptable 0,00

No pictures to display