



VOLKSWAGEN Caddy: 1TVN787

Vinnumber:	WV2ZZZ2KZFX058036	Versionname:	CADDY MAXI LIFE Trendl.102PK OMBOUW Dub.
First Registrationdate:	24/11/2014	Fiscalpower:	
Expertise Mileage:	184178	Power Kw:	75
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	BINNEN 3500KM	Parking lot:	3407
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Rear parking sensors
Windows electric F	
Cruise Control	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

Winter tyres:	205/55/16/94 H Steel			
	Fr.L.	Pirelli: 7 mm	Fr.R.	Pirelli: 7 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	443,88
-------------------	--------

Interior, Dirty, Cleaning	100,00
---------------------------	--------



Interior, Damaged, Acceptable	0,00
-------------------------------	------



Windscreen, Repaired, P - Check 0,00



Door F L, Bump(s), PDR - Knock out without painting 63,00



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 280,88



Bodywork, Damaged, Acceptable 0,00

