


MERCEDES CLA: 1GSN273

Vinnnumber:	WDD1173121N089655	Versionname:	CLA BER 180 CDI 109PK
First Registrationdate:	16/04/2014	Fiscalpower:	
Expertise Mileage:	97365	Power Kw:	80
Bodytype:	Berline	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3722
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

205/55/16/91 T LightMetal				
Winter tyres:	Fr.L.	Fulda: 6 mm	Fr.R.	Fulda: 6 mm
	Re.L.	Fulda: 5,5 mm	Re.R.	Fulda: 5,5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	109,00
-------------------	--------

Covering interior front pillar L, Stain, Acceptable	0,00
---	------

No pictures to display

Bumper grille, Broken, E - Replace	109,00
------------------------------------	--------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper corner R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Sill outer R, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display