



VOLKSWAGEN Sharan: 1GCV658

Vinnumber:	WVWZZZ7NZEV016992	Versionname:	2.0 TDI
First Registrationdate:	3/01/2014	Fiscalpower:	
Expertise Mileage:	188306	Power Kw:	100
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3427
Maintenance:	DANS 20.300 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm

Assistance equipment

	Runflat	No
Total cost ex VAT		684,18
Seat cover R, Stain, Acceptable		0,00
<i>No pictures to display</i>		
Seat cover F L, Stain, Acceptable		0,00
<i>No pictures to display</i>		
Seat cover F R, Stain, Acceptable		0,00
<i>No pictures to display</i>		
Door F R, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)		382,02



Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	302,16



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	