



MERCEDES A: 1EOJ392			
Vinnumber:	WDD1760121J060470	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	6/02/2013	Fiscalpower:	
Expertise Mileage:	125500	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2811
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT 322,80

Sill outer L, Bump(s), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Rocker panel inner R L, Bump(s), Acceptable 0,00

No pictures to display

Seat cover F L, Worn, Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Dirty, Cleaning 50,00



Tailgate, Bump(s), PDR - Knock out without painting 82,80



Roof, Bump(s), Acceptable 0,00

No pictures to display