




<b>RENAULT Clio: 1GIC352</b>			
Vinnnumber:	<b>VF15RJL0H50186480</b>	Versionname:	<b>CLIO IV BER e-Expression St&amp;St 90PK</b>
First Registrationdate:	<b>13/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>89288</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Light Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1222</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>	
Windows electric F	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

<b>Limited Technical Inspection</b>			
Power steering:	<b>Yes</b>	Battery functioning:	<b>Yes</b>
Airco functioning:	<b>OK</b>	Sound engine:	<b>OK</b>
Tires wear profile:	<b>OK</b>	Clutch test:	<b>OK</b>
Idle position:	<b>OK</b>	Wiper fluid level:	<b>OK</b>
Engine startingtime:	<b>OK</b>	Lighting:	<b>OK</b>
Exhaust gass:	<b>OK</b>	Wiperblades:	<b>OK</b>
Transmission:	<b>OK</b>		
Handbrake:	<b>OK</b>		

<b>Degree of wear</b>				
	<b>185/65/15/88 T Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

<b>Assistance equipment</b>			
Repair kit:	<b>Yes</b>	Compressor:	<b>Yes</b>
Total cost ex VAT:			<b>610,00</b>
Front bumper, Scratch(es), Acceptable:			<b>0,00</b>
<i>No pictures to display</i>			
Wheel cover F R, Scratch(es), E - Replace:			<b>24,00</b>



Headrest R M, Missing, E - Replace:	<b>48,00</b>
-------------------------------------	--------------



Wheel cover R R, Scratch(es), E - Replace 24,00



Wheel cover F L, Scratch(es), E - Replace 24,00



Wheel cover R L, Scratch(es), E - Replace 24,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 246,56



Interior, Dirty, Cleaning 50,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44

