


**MERCEDES B 180 : 1EG0587**

Vinnumber:	<b>WDD2462001J127644</b>	Versionname:	<b>B 180 CDI</b>
First Registrationdate:	<b>27/11/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>136405</b>	Power Kw:	<b>80</b>
Bodytype:		Body color	<b>MET.</b>
Gearbox:	<b>MAN 6 VIT</b>	Body color	<b>Black</b>
Transmission:	<b>Front</b>	Paint type	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer	<b>Steel</b>
Maintenance	<b>OK</b>	Oil level	<b>OK</b>
Maintenance	<b>B3 IN 12900 KM</b>	Parking lot	<b>3524</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

Winter tyres:	<b>195/65/15/91 T Steel</b>			
	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Repair kit	<b>No</b>	Compressor	<b>Yes</b>
------------	-----------	------------	------------

Total cost ex VAT	<b>1367,86</b>
-------------------	----------------

Bonnet, Scratch(es), Acceptable	<b>0,00</b>
---------------------------------	-------------

*No pictures to display*






Wheel cover F L, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Wing F L, Bump(s), PDR - Knock out without painting	<b>63,00</b>
---	--------------



Wing R R, Bump(s), Acceptable	<b>0,00</b>
-------------------------------	-------------

<i>No pictures to display</i>		
Wheel cover F R, Scratch(es), E - Replace		30,00
		
Tyre repair kit, Missing, E - Replace		38,10
		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wheel cover R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R L, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Rearview mirror housing R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Gear shift lever cover, Worn, Acceptable		0,00
<i>No pictures to display</i>		
Tailgate, Scratch(es), It - Spot repair		115,56
		
Wheel cover R R, Scratch(es), E - Replace		30,00
		
Front bumper, Broken, Le - Replace and paint		735,00
		
Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)		356,20
