



|                         |                          |              |                             |
|-------------------------|--------------------------|--------------|-----------------------------|
| <b>AUDI A3: NL6803</b>  |                          |              |                             |
| Vinnnumber:             | <b>WAUZZZ8V5EA130582</b> | Versionname: | <b>A3 SB Ambiente 150PK</b> |
| First Registrationdate: | <b>24/02/2014</b>        | Fiscalpower: |                             |
| Expertise Mileage:      | <b>61376</b>             | Power Kw:    | <b>110</b>                  |
| Bodytype:               |                          | Body color   | <b>Light Grey</b>           |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>              |
| Transmission:           |                          | Rims summer  | <b>Aluminium</b>            |
| Fueltype:               | <b>Diesel</b>            | Oil level    | <b>OK</b>                   |
| Battery functioning     | <b>Yes</b>               | Parking lot  | <b>2723</b>                 |
| Number of doors         | <b>5</b>                 |              |                             |
| Number of seats         | <b>5</b>                 |              |                             |
| Number head rests       | <b>5</b>                 |              |                             |
| Rims summer             | <b>Aluminium</b>         |              |                             |
| Category                | <b>Passenger Car</b>     |              |                             |
| Oil level               | <b>OK</b>                |              |                             |

|                                |                              |
|--------------------------------|------------------------------|
| <b>Options</b>                 |                              |
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Type of headlighting           | <b>Headlighting Xenon</b>    |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining semi-leather</b>   |
| Type of climate control        | <b>Autom climate control</b> |

|                                     |            |                     |            |
|-------------------------------------|------------|---------------------|------------|
| <b>Limited Technical Inspection</b> |            |                     |            |
| Power steering                      | <b>Yes</b> | Battery functioning | <b>Yes</b> |
| Airco functioning                   | <b>OK</b>  | Sound engine        | <b>OK</b>  |
| Tires wear profile                  | <b>OK</b>  | Clutch test         | <b>OK</b>  |
| Idle position                       | <b>OK</b>  | Wiper fluid level   | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b>  | Lighting            | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b>  | Wiperblades         | <b>OK</b>  |
| Transmission                        | <b>OK</b>  |                     |            |
| Handbrake                           | <b>OK</b>  |                     |            |

|                       |                                  |                       |       |                       |
|-----------------------|----------------------------------|-----------------------|-------|-----------------------|
| <b>Degree of wear</b> |                                  |                       |       |                       |
|                       | <b>205/55/16/91 H LightMetal</b> |                       |       |                       |
| Winter tyres:         | Fr.L.                            | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|                       | Re.L.                            | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

|                             |            |      |            |
|-----------------------------|------------|------|------------|
| <b>Assistance equipment</b> |            |      |            |
| Spare tyre compact          | <b>Yes</b> | Jack | <b>Yes</b> |

|                          |               |
|--------------------------|---------------|
| <b>Total cost ex VAT</b> | <b>394,56</b> |
|--------------------------|---------------|

|  |               |
|--|---------------|
| <b>Rocker panel inner R L, Bump(s) and scratch(es), LI - Repair and paint (complete)</b> | <b>115,56</b> |
|--|---------------|



|   |              |
|---|--------------|
| <b>Alloy rim F L, Scratch(es), LI - Repair and paint (complete)</b> | <b>95,00</b> |
|---|--------------|





Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Luggage space cover, Damaged, Repair/replace (lump sum) 64,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 25,00

