


**AUDI A6 AVANT: 1JPT707**

Vinnumber:	<b>WAUZZZ4G7FN056129</b>	Versionname:	<b>2.0 TDI ULTRA 140KW S TRONIC S LINE</b>
First Registrationdate:	<b>3/02/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>44278</b>	Power Kw:	<b>140</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2619</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats R heated	
GPS storage	<b>HD</b>	Seats electric F L	
GPS storage		Seats electric F R	
Windows electric F		Sun Roof electric	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunction		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	<b>Headlighting LED</b>	Type of Tow bar	<b>Tow bar fixed</b>
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		
Sport seats			

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>255/40/19/100 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 7,5 mm</b>	Re.R.	<b>Michelin: 7,5 mm</b>

**Assistance equipment**

Spare tyre compact	<b>Yes</b>	Jack	<b>Yes</b>
--------------------	------------	------	------------

Total cost ex VAT	<b>1517,51</b>
-------------------	----------------

Bumper R, Scratch(es), It - Spot repair	<b>115,56</b>
---	---------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------



Window F L door, Scratch(es), E - Replace 0,00



Windscreen, Stone chip(s), E - Replace 0,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 369,84



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

LED headlight L, Scratch(es), E - Replace 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Scratch(es), LI - Repair and paint (complete) 348,09



Rear window, Scratch(es), E - Replace 0,00





Tailgate, Scratch(es), LI - Repair and paint (complete)	362,02
---	--------



Rearlight L tailgate, Damaged, E - Replace	132,00
--	--------

