


**BMW 3: 1EPT552**

Vinnnumber:	<b>WBA3D91070F404590</b>	Versionname:	<b>3 BER 316d 116PK</b>
First Registrationdate:	<b>18/02/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>156211</b>	Power Kw:	<b>85</b>
Bodytype:		Body color	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>1230</b>
Number of doors	<b>4</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/60/16/92 H Steel</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 6 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Uniroyal: 6 mm</b>	Re.R.	<b>Uniroyal: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	313,36
-------------------	--------

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

*No pictures to display*

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56
--------------------------------------------------------------------------	--------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Wheel cover F L, Damaged, E - Replace	30,00
---------------------------------------	-------



Wheel cover F R, Scratch(es), E - Replace 30,00



Tailgate, Bump(s), PDR - Knock out without painting 82,80



Wheel cover R R, Scratch(es), E - Replace 30,00



Roof, Bump(s), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 25,00

