



BMW X1: 1FQJ388

Vinnumber:	WBAVY11000VW90593	Versionname:	X1 sDrive16 116PK
First Registrationdate:	23/09/2013	Fiscalpower:	
Expertise Mileage:	131671	Power Kw:	85
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:			
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Degree of wear

	225/50/17/99 MS Steel			
Winter tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment

Total cost ex VAT	528,35
Door F R, Scratch(es), LI - Repair and paint (complete)	318,35



Wheel cover F R, Scratch(es), E - Replace	30,00
-------------------------------------------	-------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Wheel cover F L, Scratch(es), E - Replace	30,00
-------------------------------------------	-------

