



AUDI A4 Allroad: 1FCY704			
Vinnnumber:	WAUZZZ8K3DA249820	Versionname:	A4 ALLROAD Quattro
First Registrationdate:	28/05/2013	Fiscalpower:	136PK
Expertise Mileage:	181701	Power Kw:	100
Bodytype:	Break	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4331
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Sun Roof electric	
GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	225/55/17/101 V LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment			
Spare tyre compact	Yes	Jack	Yes
Total cost ex VAT			5667,62
Roof, Chemical polution, LI - Repair and paint (complete)			577,80



Bumper R, Damaged, Le - Replace and paint			766,80
---	--	--	---------------



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Damaged, Le - Replace and paint 862,80



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Wing trim R L, Scratch(es), E - Replace 96,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Xenon headlight L, Damaged, E - Replace 696,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing trim R R, Scratch(es), E - Replace 96,00



Bonnet, Damaged, Le - Replace and paint 1205,64



Wing F L, Damaged, Le - Replace and paint 612,02



Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper moulding R L, Damaged, E - Replace 150,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing moulding F L, Damaged, E - Replace 109,00



Sill outer L, Scratch(es), It - Spot repair 115,56

