



BMW 1: 1HZA838

Vinnumber:	WBA1C91030P873132	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	10/11/2014	Fiscalpower:	
Expertise Mileage:	77432	Power Kw:	85
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4117
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 H Steel			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2763,87
-------------------	---------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover F R, Damaged, E - Replace	30,00
---------------------------------------	-------



Bumper R, Broken, Le - Replace and paint	651,00
--	--------



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 290,08



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 349,68



Seat cover R, Stain, Cleaning 25,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Roof pillar R, Scratch(es), It - Spot repair 115,56



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Wing F L, Bump(s), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 414,35



Wheel cover R L, Scratch(es), E - Replace 30,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Door F L, Bump(s), Acceptable 0,00

No pictures to display