



AUDI A5: 1EPB900

Vinnumber:	WAUZZZ8T1DA049933	Versionname:	A5 SB TDie DPF 136PK
First Registrationdate:	12/02/2013	Fiscalpower:	
Expertise Mileage:	171947	Power Kw:	100
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1408
Maintenance:	10100 KM OF 540 DGN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/50/17/98 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	1120,80
-------------------	----------------

Door R R, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Wing R L, Bump(s), LI - Repair and paint (complete) 308,20



Seat cover R, Stain, Cleaning 25,00



Alloy rim R L, Damaged, LI - Repair and paint (complete) 95,00



Seat cover F R, Stain, Cleaning 25,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Bump(s), PDR - Knock out without painting 82,80



Seat cover F L, Stain, Cleaning 25,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Stone chip(s), P - Check 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80

