


BMW 3: 1FXC164

Vinnumber:	WBA3Y11050D448072	Versionname:	3 GRAN TURISMO 318d 136PK
First Registrationdate:	25/11/2013	Fiscalpower:	
Expertise Mileage:	105118	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3130
Maintenance:	SERVICE IN 6000KM 11 2018		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining artificial leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 7 mm	Fr.R.	Dunlop: 7 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1900,15
-------------------	----------------

Roof pillar L, Bump(s), Acceptable	0,00
------------------------------------	-------------

No pictures to display

Interior, No damage, Acceptable	0,00
---------------------------------	-------------



Windscreen, Repaired, P - Check	0,00
---------------------------------	-------------



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bump(s), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Roof, Bump(s), PDR - Knock out without painting 300,60



Bonnet, Bump(s), PDR - Knock out without painting 241,20



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35

