



AUDI Q5: 1KJD590			
Vinnumber:	<b>WAUZZZ8R9FA123073</b>	Versionname:	<b>2.0 TDI 110KW</b>
First Registrationdate:	<b>11/05/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>170835</b>	Power Kw:	<b>110</b>
Bodytype:	<b>SUV</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4606</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Seats F L ventilated
Radio multimedia	Seats F R ventilated
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>
	Central consol F
	Luggage cover
	Front parking sensors
	Rear parking sensors

Limited Technical Inspection			
Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

Degree of wear				
Winter tyres:	<b>235/65/17/108 V LightMetal</b>			
	Fr.L.	<b>Uniroyal: 5 mm</b>	Fr.R.	<b>Uniroyal: 5 mm</b>
	Re.L.	<b>Uniroyal: 6 mm</b>	Re.R.	<b>Uniroyal: 6 mm</b>

Assistance equipment	
Repair kit	<b>Yes</b>
Compressor	<b>Yes</b>

Total cost ex VAT	<b>1375,86</b>
Wing R R, Scratch(es), LI - Repair and paint (complete)	<b>369,84</b>



Door R R, Scratch(es), LI - Repair and paint (complete)	<b>382,02</b>
---	---------------



Wing R L, Scratch(es), LI - Repair and paint (complete)	<b>369,84</b>
---	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

*No pictures to display*