


**AUDI A6: 1HZG472**

|                                    |                               |              |                       |
|------------------------------------|-------------------------------|--------------|-----------------------|
| Vinnumber:                         | <b>WAUZZZ4G0EN199485</b>      | Versionname: | <b>A6 AVANT 136PK</b> |
| First Registrationdate:            | <b>5/11/2014</b>              | Fiscalpower: |                       |
| Expertise Mileage:                 | <b>143954</b>                 | Power Kw:    | <b>100</b>            |
| Bodytype:                          |                               | Body color:  | <b>Dark Grey</b>      |
| Gearbox:                           | <b>MAN 6 VIT</b>              | Paint type:  | <b>Metalic</b>        |
| Transmission:                      | <b>Front</b>                  | Rims summer: | <b>Aluminium</b>      |
| Fueltype:                          | <b>Diesel</b>                 | Oil level:   | <b>OK</b>             |
| Maintenance:                       | <b>SERVICE IN 6100KM 517D</b> | Parking lot: | <b>3413</b>           |
| Maintenance:                       | <b>OK</b>                     |              |                       |
| Battery functioning:               | <b>Yes</b>                    |              |                       |
| Number of doors:                   | <b>5</b>                      |              |                       |
| Number of seats:                   | <b>5</b>                      |              |                       |
| Number head rests:                 | <b>5</b>                      |              |                       |
| Rims summer:                       | <b>Aluminium</b>              |              |                       |
| Category:                          | <b>Passenger Car</b>          |              |                       |
| Oil level:                         | <b>OK</b>                     |              |                       |
| Registration Certificate Car (BE): | <b>Yes</b>                    |              |                       |

**Options**

|                                |                              |                       |
|--------------------------------|------------------------------|-----------------------|
| Radio CD                       |                              | Central consol F      |
| GPS storage                    | <b>SD</b>                    | Luggage cover         |
| GPS storage                    |                              | Front parking sensors |
| Windows electric F             |                              | Rear parking sensors  |
| Windows electric R             |                              |                       |
| Cruise Control                 |                              |                       |
| Steering wheel multifunctional |                              |                       |
| Radio multimedia               |                              |                       |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |
| Type of Lining                 | <b>Lining fabrics</b>        |                       |
| Type of climate control        | <b>Autom climate control</b> |                       |

**Limited Technical Inspection**

|                     |            |                     |            |
|---------------------|------------|---------------------|------------|
| Power steering      | <b>Yes</b> | Battery functioning | <b>Yes</b> |
| Airco functioning   | <b>OK</b>  | Sound engine        | <b>OK</b>  |
| Tires wear profile  | <b>OK</b>  | Clutch test         | <b>OK</b>  |
| Idle position       | <b>OK</b>  | Wiper fluid level   | <b>OK</b>  |
| Engine startingtime | <b>OK</b>  | Lighting            | <b>OK</b>  |
| Exhaust gass        | <b>OK</b>  | Wiperblades         | <b>OK</b>  |
| Transmission        | <b>OK</b>  |                     |            |
| Handbrake           | <b>OK</b>  |                     |            |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>225/60/16/98 H LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Bridgestone: 5 mm</b> | Fr.R. | <b>Bridgestone: 6 mm</b> |
|               | Re.L.                            | <b>Goodyear: 6 mm</b>    | Re.R. | <b>Goodyear: 6 mm</b>    |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

**Total cost ex VAT** 886,40

**Front bumper, Scratch(es), LI - Repair and paint (complete)** 254,16

**Windscreen, Stone chip(s), E - Replace** 560,64



|  |       |
|--|-------|
| Engine protective plate, Hole, E - Replace | 71,60 |
|--|-------|



|                                 |      |
|---------------------------------|------|
| Interior, No damage, Acceptable | 0,00 |
|---------------------------------|------|

