


BMW 1: 1FPE659

Vinnnumber:	WBA1C91010J516311	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	12/09/2013	Fiscalpower:	
Expertise Mileage:	168352	Power Kw:	85
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2733
Maintenance	23/02/2018		
Maintenance	168208		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Manual climate control	
Adaptive cruise control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/94 V LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 8 mm	Re.R.	Bridgestone: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 558,36

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00




Rear wiper blade, Tear, E - Replace 28,76



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper grille F R, Broken, E - Replace 32,40



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Interior, Damaged, Acceptable 0,00



Bodywork, Damaged, Acceptable 0,00



Bumper grille, Broken, E - Replace 32,40



Door F R, Bump(s), PDR - Knock out without painting 63,00

