



BMW 3: JV4513			
Vinnumber:	WBA3D91020F405484	Versionname:	3 BER 316d 116PK
First Registrationdate:	29/04/2016	Fiscalpower:	
Expertise Mileage:	163900	Power Kw:	85
Bodytype:	Berline	Body color	Silver
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3105
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
GPS storage	HD	Rear parking sensors	
GPS storage			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	205/60/16/99 MS Steel			
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			850,35
Wheel cover R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wheel cover F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Scratch(es), LI - Repair and paint (complete)			318,35



Boot carpet, Stain, Forfeit			12,00
-----------------------------	--	--	--------------



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display