


BMW 4 GRAN COUPE: HP5441

Vinnnumber:	WBA4B31090G588450	Versionname:	3.0 435I XDRIVE 4WD GRAN COUPE
First Registrationdate:	24/02/2016	Fiscalpower:	
Expertise Mileage:	69729	Power Kw:	225
Bodytype:	Berline	Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2606
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Laser	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/45/18/95 V LightMetal			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

 Runflat **Yes**

Total cost ex VAT	343,60
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Tyre R L, Damaged, E - Replace	153,60
--------------------------------	--------



Roof pillar L, Scratch(es), Acceptable	0,00
--	------

No pictures to display