



AUDI A4: 1EQN981			
Vinnumber:	WAUZZZ8K1DA200759	Versionname:	A4 BER TDie 136PK
First Registrationdate:	25/02/2013	Fiscalpower:	
Expertise Mileage:	147476	Power Kw:	100
Bodytype:		Body color:	Light Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4120
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunction	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Fulda: 9 mm	Fr.R.	Fulda: 9 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment	
Total cost ex VAT	1037,36
Rearview mirror housing L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00





Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Stone chip(s), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

