



|                         |                          |              |                                |
|-------------------------|--------------------------|--------------|--------------------------------|
| <b>BMW 5: WN4810</b>    |                          |              |                                |
| Vinnnumber:             | <b>WBA5B91010D566340</b> | Versionname: | <b>5 BER 520dXA 184PK Aut.</b> |
| First Registrationdate: | <b>17/01/2014</b>        | Fiscalpower: |                                |
| Expertise Mileage:      | <b>105814</b>            | Power Kw:    | <b>135</b>                     |
| Bodytype:               |                          | Body color:  | <b>White</b>                   |
| Gearbox:                | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                 |
| Transmission:           |                          | Rims summer: | <b>Aluminium</b>               |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                      |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>2509</b>                    |
| Number of doors:        | <b>4</b>                 |              |                                |
| Number of seats:        | <b>5</b>                 |              |                                |
| Number head rests:      | <b>5</b>                 |              |                                |
| Rims summer:            | <b>Aluminium</b>         |              |                                |
| Category:               | <b>Passenger Car</b>     |              |                                |
| Oil level:              | <b>OK</b>                |              |                                |

|                                |                              |
|--------------------------------|------------------------------|
| <b>Options</b>                 |                              |
| Radio CD                       | Central consol F             |
| Windows electric F             | Front parking sensors        |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Seats F heated                 |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Xenon</b>    |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining leather</b>        |
| Type of climate control        | <b>Autom climate control</b> |

|                                     |            |                     |            |
|-------------------------------------|------------|---------------------|------------|
| <b>Limited Technical Inspection</b> |            |                     |            |
| Power steering                      | <b>Yes</b> | Battery functioning | <b>Yes</b> |
| Airco functioning                   | <b>OK</b>  | Sound engine        | <b>OK</b>  |
| Tires wear profile                  | <b>OK</b>  | Clutch test         | <b>OK</b>  |
| Idle position                       | <b>OK</b>  | Wiper fluid level   | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b>  | Lighting            | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b>  | Wiperblades         | <b>OK</b>  |
| Transmission                        | <b>OK</b>  |                     |            |
| Handbrake                           | <b>OK</b>  |                     |            |

|                       |                                   |                          |       |                          |
|-----------------------|-----------------------------------|--------------------------|-------|--------------------------|
| <b>Degree of wear</b> |                                   |                          |       |                          |
| Winter tyres:         | <b>245/45/18/100 V LightMetal</b> |                          |       |                          |
|                       | Fr.L.                             | <b>Continental: 4 mm</b> | Fr.R. | <b>Continental: 4 mm</b> |
|                       | Re.L.                             | <b>Continental: 3 mm</b> | Re.R. | <b>Continental: 3 mm</b> |

|   |            |
|---|------------|
| <b>Assistance equipment</b>                             |            |
| Compressor  | <b>Yes</b> |
| Total cost ex VAT                                       | 349,16     |
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 254,16     |



|  |       |
|--|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



|  |      |
|--|------|
| Bumper F R, Scratch(es), Acceptable    | 0,00 |
| <i>No pictures to display</i>          |      |
| Alloy rim R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>          |      |