



MERCEDES CLA: 1FXC563

Vinnnumber:	WDD1173011N056122	Versionname:	CLA BER 200 CDI 136PK
First Registrationdate:	25/11/2013	Fiscalpower:	
Expertise Mileage:	69869	Power Kw:	100
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4208
Number of doors:	4		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunction	
Alarm	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	278,56
-------------------	--------

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Door F R, Repaired, P - Check	0,00
-------------------------------	------



Interior, Dirty, Cleaning	100,00
---------------------------	--------



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Bump(s), PDR - Knock out without painting	63,00



Bumper moulding R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Repaired, P - Check	0,00



Bumper F L, Scratch(es), It - Spot repair	115,56
---	--------



Door F L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Repaired, P - Check	0,00

