



FORD C-MAX: 1CCE037

Vinnumber:	WFOJXXWPBJBJ46134	Versionname:	C-MAX Trend St/St 95PK
First Registrationdate:	17/10/2011	Fiscalpower:	
Expertise Mileage:	176775	Power Kw:	70
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3827
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Luggage cover	
GPS storage		Rear parking sensors	
GPS storage	SD		
Windows electric F			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	215/55/16/93 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 5,5 mm	Fr.R.	Uniroyal: 5,5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	2269,18
-------------------	---------

Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------




Rearview mirror R complete, Damaged, Le - Replace and paint	283,00
---	--------



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 370,00



Windscreen, Scratch(es), E - Replace 487,20



Door panel F L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Luggage space cover, Missing, E - Replace 240,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Centre console, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Door panel R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper spoiler F, Damaged, E - Replace 54,00



Spoiler R, Damaged, Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Stain, Cleaning 75,00



Door panel F L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Tailgate, Rust, Acceptable	0,00
----------------------------	------

No pictures to display

Door panel R L, Damaged, E - Replace	138,00
--------------------------------------	--------

