


BMW X5: 1ETC777

Vinnnumber:	WBAZW410X00C18068	Versionname:	X5 3.0d xDrive30 211PK
First Registrationdate:	14/03/2013	Fiscalpower:	Aut.
Expertise Mileage:	102577	Power Kw:	155
Bodytype:	SUV	Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2833
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunction		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	NOT OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	255/55/18/109 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

 Runflat **Yes**





 Total cost ex VAT **388,20**

 Armrest F Mid, Scratch(es), Acceptable **0,00**
No pictures to display

 Wing F R, Bump(s), PDR - Knock out without painting **63,00**

 Rearview mirror housing L, Scratch(es), Acceptable **0,00**
No pictures to display

 Rocker panel inner R L, Scratch(es), Acceptable **0,00**

<i>No pictures to display</i>		
Door R R, Bump(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R L, Bump(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door panel R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Bump(s), PDR - Knock out without painting		63,00
		
Windscreen, Stone chip(s), Windscreen repair		88,20
		
		
Wing R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper grille F R, Broken, E - Replace		174,00
		
Maintenance, Maintenance, Execute		0,00
<i>No pictures to display</i>		