






BMW X3: HA9581			
Vinnumber:	WBAWZ510X00M04951	Versionname:	X3 2.0d xDrive20 190PK
First Registrationdate:	5/12/2014	Fiscalpower:	
Expertise Mileage:	137378	Power Kw:	140
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2204
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		


Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	225/60/17/99 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 6 mm	Fr.R.	Dunlop: 6 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT		900,39	
Door R L, Scratch(es), Acceptable		0,00	
<i>No pictures to display</i>			
Bonnet, Stone chip(s), Acceptable		0,00	
<i>No pictures to display</i>			
Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)		264,21	

			
Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)			382,02



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Door F L, Scratch(es), Acceptable 0,00

No pictures to display