


FORD Mondeo: 1FRV316

| | | | |
|------------------------------------|--|--------------|---|
| Vinnumber: | WF0GXXGBBGDG62794 | Versionname: | MONDEO CLIP ECONetic Trend Style 115PK |
| First Registrationdate: | 4/10/2013 | Fiscalpower: | |
| Expertise Mileage: | 94679 | Power Kw: | 85 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | LAATSTE ONDERHOUD OP 79572KM 4 2017 | Parking lot: | 4220 |
| Maintenance: | OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Seats electric F L |
| GPS storage | | Central consol F |
| GPS storage | HD | Luggage cover |
| Windows electric F | | Front parking sensors |
| Windows electric R | | Rear parking sensors |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting: | Headlighting Halogen | |
| Type of GPS: | GPS big screen color | |
| Type of Lining: | Lining fabrics | |
| Type of climate control: | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|------------|---------------------|------------|
| Power steering | Yes | Battery functioning | Yes |
| Airco functioning | OK | Sound engine | OK |
| Tires wear profile | OK | Clutch test | OK |
| Idle position | OK | Wiper fluid level | OK |
| Engine startingtime | OK | Lighting | OK |
| Exhaust gass | OK | Wiperblades | OK |
| Transmission | OK | | |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|-------------------------|-------|-------------------------|
| | 215/55/16/93 H LightMetal | | | |
| Winter tyres: | Fr.L. | Vredestein: 7 mm | Fr.R. | Vredestein: 7 mm |
| | Re.L. | Goodyear: 6 mm | Re.R. | Goodyear: 6 mm |

Assistance equipment

| | | | |
|--------------------|------------|------|------------|
| Spare tyre compact | Yes | Jack | Yes |
|--------------------|------------|------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 211,80 |
|-------------------|--------|

| | |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---------------------------------------|------|
| Front bumper, Scratch(es), Acceptable | 0,00 |
|---------------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|----------------------------|------|
| Interior, Worn, Acceptable | 0,00 |
|----------------------------|------|



| | |
|--------------------------------------|------|
| Floor covering F L, Worn, Acceptable | 0,00 |
|--------------------------------------|------|

No pictures to display

| | |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|

