



BMW 5: 1DRJ841

Vinnumber:	WBAMX11010DY03598	Versionname:	5 TOURING 520dA Start/Stop 163PK aut
First Registrationdate:	1/08/2012	Fiscalpower:	
Expertise Mileage:	101994	Power Kw:	120
Bodytype:	Break	Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4124
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1446,08

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 326,16





Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Electricity circuit, No damage, No repair 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Bump(s), PDR - Knock out without painting 63,00



Door F R, Repaired, Acceptable 0,00

No pictures to display

Wing R R, Repaired, Acceptable 0,00

No pictures to display

Tyre R R, Damaged, E - Replace 153,60



Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16





Tyre F L, Damaged, E - Replace 153,60



Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Repaired, Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56

