



FORD Grand C-Max: 1EQM764

| | | | |
|-------------------------|---|--------------|-----------------------------|
| Vinnnumber: | WF0HXXWPBHDJ81552 | Versionname: | GR.C-MAX Trend St/St |
| First Registrationdate: | 22/02/2013 | Fiscalpower: | 95PK |
| Expertise Mileage: | 112182 | Power Kw: | 70 |
| Bodytype: | | Body color | Grey |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | Front | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Maintenance | OK | Parking lot | 1117 |
| Maintenance | LAATSTE ONDERHOUD OP 100380KM 8 2017 | | |
| Battery functioning | Yes | | |
| Number of doors | 5 | | |
| Number of seats | 5 | | |
| Number head rests | 5 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |

Options

| | | |
|--------------------------------|------------------------------|----------------------|
| Radio CD | | Central consol F |
| GPS storage | SD | Luggage cover |
| GPS storage | | Rear parking sensors |
| Windows electric F | | |
| Windows electric R | | |
| Steering wheel multifunctional | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|------------|---------------------|------------|
| Power steering | Yes | Battery functioning | Yes |
| Airco functioning | OK | Sound engine | OK |
| Tires wear profile | OK | Clutch test | OK |
| Idle position | OK | Wiper fluid level | OK |
| Engine startingtime | OK | Lighting | OK |
| Exhaust gass | OK | Wiperblades | OK |
| Transmission | OK | | |
| Handbrake | OK | | |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 215/55/16/97 H LightMetal | | | |
| Winter tyres: | Fr.L. | Bridgestone: 3 mm | Fr.R. | Bridgestone: 3 mm |
| | Re.L. | Bridgestone: 7 mm | Re.R. | Bridgestone: 6 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 211,80 |
|-------------------|---------------|

| | |
|--|-------------|
| Bumper Trim F, Scratch(es), Acceptable | 0,00 |
|--|-------------|

No pictures to display

| | |
|---------------------------------|-------------|
| Windscreen, Repaired, P - Check | 0,00 |
|---------------------------------|-------------|



| | |
|-----------------------------------|-------------|
| Door R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|-------------------------------|-------------|
| Wing R R, Bump(s), Acceptable | 0,00 |
|-------------------------------|-------------|

