


**BMW X1: 1EXW897**

|                                    |                          |              |                          |
|------------------------------------|--------------------------|--------------|--------------------------|
| Vinnnumber:                        | <b>WBAVY110X0VW88849</b> | Versionname: | <b>X1 sDrive16 116PK</b> |
| First Registrationdate:            | <b>17/04/2013</b>        | Fiscalpower: |                          |
| Expertise Mileage:                 | <b>169665</b>            | Power Kw:    | <b>85</b>                |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>Dark Grey</b>         |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>           |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>         |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4813</b>              |
| Number of doors:                   | <b>5</b>                 |              |                          |
| Number of seats:                   | <b>5</b>                 |              |                          |
| Number head rests:                 | <b>5</b>                 |              |                          |
| Rims summer:                       | <b>Aluminium</b>         |              |                          |
| Category:                          | <b>VS</b>                |              |                          |
| Oil level:                         | <b>OK</b>                |              |                          |
| Registration Certificate Car (BE): | <b>No</b>                |              |                          |

**Options**

|                                |  |                      |                          |
|--------------------------------|--|----------------------|--------------------------|
| Radio CD                       |  | Central consol F     |                          |
| GPS storage                    |  | Luggage cover        |                          |
| GPS storage                    | <b>HD</b>                                      | Rear parking sensors |                          |
| Windows electric F             |  | Type of Tow bar      | <b>Tow bar removable</b> |
| Windows electric R             |  |                      |                          |
| Cruise Control                 |  |                      |                          |
| Steering wheel multifunctional |  |                      |                          |
| Radio multimedia               |  |                      |                          |
| Type of headlighting           | <b>Headlighting Halogen</b>                    |                      |                          |
| Type of GPS                    | <b>GPS big screen color</b>                    |                      |                          |
| Type of Lining                 | <b>Lining artificial leather and alcantara</b> |                      |                          |
| Level control                  |  |                      |                          |

**Limited Technical Inspection**

|                     |            |                     |            |
|---------------------|------------|---------------------|------------|
| Power steering      | <b>Yes</b> | Battery functioning | <b>Yes</b> |
| Airco functioning   | <b>OK</b>  | Sound engine        | <b>OK</b>  |
| Tires wear profile  | <b>OK</b>  | Clutch test         | <b>OK</b>  |
| Idle position       | <b>OK</b>  | Wiper fluid level   | <b>OK</b>  |
| Engine startingtime | <b>OK</b>  | Lighting            | <b>OK</b>  |
| Exhaust gass        | <b>OK</b>  | Wiperblades         | <b>OK</b>  |
| Transmission        | <b>OK</b>  |                     |            |
| Handbrake           | <b>OK</b>  |                     |            |

**Degree of wear**





|               | <b>225/50/17/98 V LightMetal</b> |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| Summer tyres: | Fr.L.                            | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|               | Re.L.                            | <b>Uniroyal: 6 mm</b> | Re.R. | <b>Uniroyal: 6 mm</b> |

**Assistance equipment**

|                    |           |            |           |
|--------------------|-----------|------------|-----------|
| Spare wheel        | <b>No</b> | Compressor | <b>No</b> |
| Spare tyre compact | <b>No</b> | Runflat    | <b>No</b> |
| Repair kit         | <b>No</b> |            |           |

|   |        |
|---|--------|
| Total cost ex VAT                                   | 655,14 |
| Wing R L, Scratch(es), Acceptable                   | 0,00   |
| <i>No pictures to display</i>                       |        |
| Alloy rim F R, Scratch(es), Acceptable              | 0,00   |
| <i>No pictures to display</i>                       |        |
| Door F R, Bump(s), PDR - Knock out without painting | 63,00  |



|  |        |
|--|--------|
| Seat cover F L, Worn, P - Check  | 0,00   |
|    |        |
| Windscreen, Stone chip(s), Acceptable  | 0,00   |
| <i>No pictures to display</i>  |        |
| Door R L, Bump(s), Acceptable  | 0,00   |
| <i>No pictures to display</i>  |        |
| Bumper R, Scratch(es), Smart repair  | 110,64 |
|   |        |
| Tyre repair kit, Missing, P - Check  | 0,00   |
|   |        |
| Roof, Chemical polution, LI - Repair and paint (complete)                          | 481,50 |
|  |        |
| Bonnet, Bump(s), Acceptable  | 0,00   |
| <i>No pictures to display</i>  |        |