



PEUGEOT 308 SW: 1FWU391

Vinnumber:	VF34E9HP0DS216808	Versionname:	1.6 HDI
First Registrationdate:	21/11/2013	Fiscalpower:	
Expertise Mileage:	160391	Power Kw:	68
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3526
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Other: 4 mm	Fr.R.	Other: 4 mm
	Re.L.	Other: 5 mm	Re.R.	Other: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 943,89

Ignition key, Missing, P - Check 0,00



Roof, Bump(s), PDR - Knock out without painting 63,00



Wheel cover R L, Scratch(es), E - Replace 30,00



Bumper R, Scratch(es), 67 - Polish 55,19



Door R R, Bump(s), PDR - Knock out without painting 102,60



Roof pillar L, Bump(s), Acceptable 0,00

No pictures to display

Door F R, Bump(s), Acceptable 0,00

No pictures to display

Bumper grille, Broken, E - Replace 122,51



Wheel cover F R, Scratch(es), E - Replace 30,00



Wheel cover F L, Scratch(es), E - Replace 30,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s), PDR - Knock out without painting 102,60



Rear spoiler, Bump(s), LI - Repair and paint (complete) 211,56



Wheel cover R R, Scratch(es), E - Replace 30,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), 67 - Polish 55,19



Sill R L, Damaged, E - Replace 111,24

