



OPEL Astra: 1EQL165

Vinnumber:	WOLPE8EW5D8028443	Versionname:	ASTRA BRE ecoFLEX Cosmo St/St 110PK
First Registrationdate:	22/02/2013	Fiscalpower:	
Expertise Mileage:	108950	Power Kw:	81
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3832
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	225/50/17/98 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	376,92
Windscreen, Stone chip(s), Windscreen repair	58,80



Bumper spoiler F, Damaged, E - Replace	42,00
--	-------



Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Rocker panel inner F L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Floor covering F L, Hole, Smart repair	64,32
--	-------



Wing R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display