



OPEL Movano 2800 SWB: 523AKB

Vinnnumber:	VN1F9A2D641102656	Versionname:	MOVANO 2800 B/F L1H1 100PK
First Registrationdate:	31/03/2009	Fiscalpower:	
Expertise Mileage:	90811	Power Kw:	74
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV28
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	NOT OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	NOT OK		
Handbrake	OK		

Degree of wear

	195/65/16/100 T Steel			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			818,14
Bumper R, Scratch(es), Smart repair			110,64



Trunk door R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Outer door handle R R, Damaged, E - Replace	64,00



Tailgate lock, Strained , E - Replace	108,00
---------------------------------------	---------------



Wing R L, Bump(s), PDR - Knock out without painting 82,80



Front bumper, Crack, E - Replace 398,40



Bumper grille, Damaged, E - Replace 30,30



Door F L, Bump(s), Acceptable 0,00

No pictures to display

Sliding door R, Scratch(es), Acceptable 0,00

No pictures to display

Molding trunk, Missing, E - Replace 24,00

