



OPEL Astra: 1FWR956

Vinnumber:	W0LPD8EW3E8019566	Versionname:	ASTRA BRE ecoFLEX Business 110PK
First Registrationdate:	20/11/2013	Fiscalpower:	
Expertise Mileage:	109358	Power Kw:	81
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1606
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1512,24
-------------------	----------------

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	404,20
---	---------------



Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	---------------




Front bumper, Bad repair, Paint	0,00
---------------------------------	-------------



Tailgate, Bump(s), Le - Replace and paint	0,00
---	------



Wing F R, Bad repair, Paint	0,00
-----------------------------	------



Bumper grille F R, Incomplete, E - Replace	32,40
--	-------



Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	115,56
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Wing F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Bonnet, Scratch(es), LI - Repair and paint (complete)	290,08
---	--------

