



PEUGEOT 2008: 1GJL141				
Vinnumber:	VF3CU8HR0EY018558	Versionname:	2008 Active 68PK	
First Registrationdate:	24/02/2014	Fiscalpower:		
Expertise Mileage:	82541	Power Kw:	50	
Bodytype:	SUV	Body color	Dark Grey	
Gearbox:	MAN 5 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Steel	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	4222	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Steel			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Luggage cover		
Windows electric F		Rear parking sensors		
Cruise Control				
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Manual climate control			
Limited Technical Inspection				
Power steering	Yes	Battery functioning	Yes	
Airco functioning	OK	Sound engine	OK	
Tires wear profile	OK	Clutch test	OK	
Idle position	OK	Wiper fluid level	OK	
Engine startingtime	OK	Lighting	OK	
Exhaust gass	OK	Wiperblades	OK	
Transmission	OK			
Handbrake	OK			
Degree of wear				
Winter tyres:	195/60/16/89 H Steel			
	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm
Assistance equipment				
Spare tyre compact	Yes	Jack	Yes	
Total cost ex VAT			453,64	
Wing F R, Stone chip(s), Acceptable			0,00	
No pictures to display				
Bumper R, Scratch(es), Smart repair			110,64	
Wheel cover F R, Scratch(es), E - Replace			30,00	



Bonnet, Bump(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Roof, Hail damage, PDR - Hail	250,00
-------------------------------	--------



Door F L, Bump(s), PDR - Knock out without painting	63,00
---	-------

