



OPEL Astra: 1DHA970				
Vinnumber:	W0LPC8DW3C8087755	Versionname:	ASTRA BRE ecoFLEX	
First Registrationdate:	14/05/2012	Fiscalpower:	Essent.St/St DPF 110PK	
Expertise Mileage:	58451	Power Kw:	81	
Bodytype:	Break	Body color	Black	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Steel	
Fueltype:	Diesel	Oil level	OK	
Maintenance	NOT OK	Parking lot	4809	
Battery functioning	Yes			
Number of doors	5			
Number of seats	5			
Number head rests	4			
Rims summer	Steel			
Category	Passenger Car			
Oil level	OK			
Options				
Radio CD		Luggage cover		
GPS storage		Type of Tow bar	Tow bar fixed	
GPS storage	SD			
Windows electric F				
Steering wheel multifunctional				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Manual climate control			
Limited Technical Inspection				
Power steering	Yes	Battery functioning	Yes	
Airco functioning	OK	Sound engine	OK	
Tires wear profile	OK	Clutch test	OK	
Idle position	OK	Wiper fluid level	OK	
Engine startingtime	OK	Lighting	OK	
Exhaust gass	OK	Wiperblades	OK	
Transmission	OK			
Handbrake	OK			
Degree of wear				
Summer tyres:	215/60/16/95 V Steel			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Assistance equipment				
Spare wheel	Yes	Jack	Yes	
Total cost ex VAT			1375,62	
Rearview mirror housing R, Scratch(es), Acceptable			0,00	
No pictures to display				
Windscreen, Stone chip(s), Acceptable			0,00	
No pictures to display				
Bumper R, Scratch(es), Acceptable			0,00	
No pictures to display				
Door F R, Scratch(es), Acceptable			0,00	
No pictures to display				
Interior, Stain, Cleaning			75,00	





Door R L, Bump(s), PDR - Knock out without painting 63,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Maintenance, Maintenance, Execute 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 370,00



Steering wheel, Worn, Acceptable 0,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display



Wheel cover F R, Scratch(es), E - Replace 30,00



Wing R L, Bad repair, Paint 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Rear spoiler, Chemical polution, LI - Repair and paint (complete)	115,56
---	--------



Door R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display