



RENAULT Megane: 1JGA546			
Vinnnumber:	VF1KZ140652132334	Versionname:	MEGANE GT Energy Business 110PK
First Registrationdate:	9/12/2014	Fiscalpower:	
Expertise Mileage:	169763	Power Kw:	81
Bodytype:	Break	Body color	Silver
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4412
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	205/55/16/91 T Steel			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			434,80
Roof pillar R, Bump(s), Acceptable			0,00
No pictures to display			
Tailgate, Bump(s), PDR - Knock out without painting			63,00



Bonnet, Bump(s), Acceptable	0,00
No pictures to display	
Wheel cover R L, Scratch(es), Acceptable	0,00
No pictures to display	
Interior, Stain, Cleaning	100,00

Interior, Seating, Steering			10,00
			
Trunk lid covering R, Scratch(es), Acceptable			0,00
No pictures to display			
Wheel cover F L, Scratch(es), E - Replace			30,00
			
Boot carpet, Waterinfiltration, Cleaning			0,00
			
Internal Boot Lining R, Scratch(es), Acceptable			0,00
No pictures to display			
Front bumper, Scratch(es), LI - Repair and paint (complete)			211,80
			
Door R R, Repaired, Acceptable			0,00
No pictures to display			
Internal Boot Lining L, Scratch(es), Acceptable			0,00
No pictures to display			
Wheel cover R R, Scratch(es), Acceptable			0,00
No pictures to display			
Rear window, Not original part, Remove lettering			0,00
No pictures to display			
Wheel cover F R, Broken, E - Replace			30,00
			
Wing R R, Bump(s), Acceptable			0,00
No pictures to display			