



RENAULT Grand Scenic: 1ERM213			
Vinnnumber:	VF1JZ14A648605767	Versionname:	GR.SCENIC Energ.Expression 5Pl.FAP
First Registrationdate:	1/03/2013	Fiscalpower:	110PK
Expertise Mileage:	115042	Power Kw:	81
Bodytype:	Hatchback	Body color	Red
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4811
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	205/60/16/96 H Steel			
	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1150,30
Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)			318,35



Wheel cover F R, Scratch(es), E - Replace	30,00
---	--------------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Rear window, Scratch(es), E - Replace	0,00
---------------------------------------	------



Wheel cover R L, Not original part, E - Replace	30,00
---	-------



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Wheel cover F L, Missing, E - Replace	30,00
---------------------------------------	-------



Wing R R, Bad repair, Paint	0,00
-----------------------------	------



Front bumper, Bump(s), LI - Repair and paint (complete)	211,80
---	--------

