



**PEUGEOT 5008: 1ECI302**

|                         |                          |              |                              |
|-------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber:             | <b>VF30A9HR8CS235411</b> | Versionname: | <b>5008 Access FAP 112PK</b> |
| First Registrationdate: | <b>18/10/2012</b>        | Fiscalpower: |                              |
| Expertise Mileage:      | <b>105586</b>            | Power Kw:    | <b>82</b>                    |
| Bodytype:               | <b>MPV</b>               | Body color:  | <b>Dark Blue</b>             |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>               |
| Transmission:           | <b>Front</b>             | Rims summer: | <b>Steel</b>                 |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                    |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>3815</b>                  |
| Number of doors:        | <b>5</b>                 |              |                              |
| Number of seats:        | <b>5</b>                 |              |                              |
| Number head rests:      | <b>5</b>                 |              |                              |
| Rims summer:            | <b>Steel</b>             |              |                              |
| Category:               | <b>Passenger Car</b>     |              |                              |
| Oil level:              | <b>OK</b>                |              |                              |

**Options**

|                         |                              |
|-------------------------|------------------------------|
| Radio CD                | Luggage cover                |
| Windows electric F      |                              |
| Cruise Control          |                              |
| Radio multimedia        |                              |
| Type of headlighting    | <b>Headlighting Halogen</b>  |
| Type of GPS             | <b>GPS big screen color</b>  |
| Type of Lining          | <b>Lining fabrics</b>        |
| Type of climate control | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |            |                     |            |
|---------------------|------------|---------------------|------------|
| Power steering      | <b>Yes</b> | Battery functioning | <b>Yes</b> |
| Airco functioning   | <b>OK</b>  | Sound engine        | <b>OK</b>  |
| Tires wear profile  | <b>OK</b>  | Clutch test         | <b>OK</b>  |
| Idle position       | <b>OK</b>  | Wiper fluid level   | <b>OK</b>  |
| Engine startingtime | <b>OK</b>  | Lighting            | <b>OK</b>  |
| Exhaust gass        | <b>OK</b>  | Wiperblades         | <b>OK</b>  |
| Transmission        | <b>OK</b>  |                     |            |
| Handbrake           | <b>OK</b>  |                     |            |

**Degree of wear**

|               |                             |                       |       |                       |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
|               | <b>215/55/16/93 H Steel</b> |                       |       |                       |
| Winter tyres: | Fr.L.                       | <b>Uniroyal: 6 mm</b> | Fr.R. | <b>Uniroyal: 6 mm</b> |
|               | Re.L.                       | <b>Uniroyal: 7 mm</b> | Re.R. | <b>Uniroyal: 7 mm</b> |

**Assistance equipment**

|                    |            |      |            |
|--------------------|------------|------|------------|
| Spare tyre compact | <b>Yes</b> | Jack | <b>Yes</b> |
|--------------------|------------|------|------------|

|                   |         |
|-------------------|---------|
| Total cost ex VAT | 1343,66 |
|-------------------|---------|

|   |        |
|---|--------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



|   |        |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|





Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Wheel cover F R, Scratch(es), E - Replace 30,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Wheel cover R L, Missing, E - Replace 30,00



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Wheel cover F L, Missing, E - Replace 30,00

