



**RENAULT Grand Scenic: 1EOV141**

Vinnumber:	<b>VF1JZ14B648456724</b>	Versionname:	<b>GR.SCENIC Energ.Business</b>
First Registrationdate:	<b>11/02/2013</b>	Fiscalpower:	<b>7pl.FAP 110PK</b>
Expertise Mileage:	<b>117335</b>	Power Kw:	<b>81</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Burgundy</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1329</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

**Degree of wear**

	<b>205/60/16/96 H Steel</b>			
Winter tyres:	Fr.L.	<b>Continental: 6 mm</b>	Fr.R.	<b>Continental: 6 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>

**Assistance equipment**


Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	2032,84
-------------------	---------

Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Wheel cover R L, Scratch(es), E - Replace	30,00
---	-------



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Wheel cover F R, Damaged, E - Replace 30,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80




Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Interior, Dirty, Cleaning 100,00



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	310,50
---	--------



Door F R, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Bodywork, Not original part, Acceptable	0,00
---	------

*No pictures to display*

Rocker panel inner R L, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*