



RENAULT Megane: 1FWW977			
Vinnnumber:	VF1KZ140649736151	Versionname:	MEGANE GT Energy Bose Ed.110PK
First Registrationdate:	22/11/2013	Fiscalpower:	
Expertise Mileage:	139636	Power Kw:	81
Bodytype:		Body color	Red
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2715
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
GPS storage	SD Luggage cover
GPS storage	Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	205/55/17/95 H LightMetal			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment	
Spare wheel	Yes Jack Yes
Total cost ex VAT	481,88
Rearlight L, Crack, E - Replace	114,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
MOT Certificate, Missing, P - Check	0,00
<i>No pictures to display</i>	
Seat cover F R, Stain, Cleaning	25,00



Seat cover F L, Worn, P - Check	0,00
---------------------------------	------

No pictures to display

Bonnet, Bump(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Seat cover R, Stain, Cleaning	25,00
-------------------------------	-------



Rearlight R , Scratch(es), Acceptable	0,00
---------------------------------------	------



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Wing F R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Rocker panel inner R R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Ceiling, Hole, Smart repair	64,32
-----------------------------	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door trim F L, Scratch(es), LI - Repair and paint (complete)	75,00
--	-------

