


TOYOTA Grand Prius Plus: 1FQR488

Vinnnumber:	JTDZ53EU503053581	Versionname:	GRAND PRIUS+ Hybrid Comfort 99PK Aut.
First Registrationdate:	25/09/2013	Fiscalpower:	
Expertise Mileage:	96172	Power Kw:	73
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3533
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof
GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare tyre compact	Yes	Jack	Yes
--------------------	------------	------	------------

Total cost ex VAT	4036,68
-------------------	---------

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Windscreen, Broken, E - Replace	487,20
---------------------------------	--------



Roof, Hail damage, LI - Repair and paint (complete)	841,50
---	--------



Door F R, Hail damage, LI - Repair and paint (complete) 414,35



Wing F R, Hail damage, LI - Repair and paint (complete) 316,18



Wing F L, Bump(s), E - Replace 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bump(s), Le - Replace and paint 1016,70



Door R R, Hail damage, LI - Repair and paint (complete) 414,35



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Hail damage, LI - Repair and paint (complete) 404,20



Tailgate, Hail damage, PDR - Knock out without painting

142,20

